

**KRIPTONLUB 916/0****1. Identification of the substance / preparation and of the company / undertaking**

Product's Name	KRIPTONLUB 916/0
Products code	KL75097
Company identification	KRIPTON OIL, S.L. C/. Ca l'Arabia, 28 – Pol. Congost 08520 – Las Franquesas del Vallés (Barcelona) Tel.: 938 616 554 Fax: 938 464 197 <a href="http://www.krypton.es">www.krypton.es</a> @: <a href="mailto:comercial@krypton.es">comercial@krypton.es</a> En caso de emergencia: 938 616 554

**2. Hazards identification**

Symptoms relating to use	Not expected to present a significant hazard under anticipated conditions of normal.
--------------------------	--

**3. Composition / information on ingredients**

Components	This product is not hazardous.
------------	--------------------------------

**4. First aid measures**

General information	Never give anything by mouth to an unconscious person. If you feel unwell, seek medical advice (show the label where possible).
Inhalation	Assure fresh air breathing. Allow the victim to rest.
Skin contact	Remove affected clothing and wash all exposed skin area with mild soap and water, followed by warm water rinse..
Eye contact	Rinse immediately with plenty of water. Obtain medical attention if pain, blinking or redness persist..
Ingestion	Do not induce vomiting. Obtain emergency medical attention.

**5. Fire-fighting measures**

Hazardous combustion products	Under fire conditions, hazardous fumes will be present.
Surrounding fires	Use water spray or fog for cooling exposed containers.
Protection against fire	Do not enter fire area without proper protective equipment, including respiratory protection.
Special procedures	Exercise caution when fighting any chemical fire. Avoid (reject) fire-fighting water to enter environment.

**6. Accidental release measures**

Personal precautions	Equip cleanup crew with proper protection.
Environmental precautions	Prevent entry to sewers and public waters. Notify authorities if product enters sewers or public waters.
Clean up methods	Ventilate area. On land, sweep or shovel into suitable containers. Minimize generation of dust.

**7. Handling and storage**

Technical protective measures	Provide good ventilation in process area to prevent formation of vapour.
Storage	Keep only in the original container in a cool, well ventilated place. Keep container closed when not in use. Storage temperature : 5 - 40 °C.
Storage - away from	Strong bases. Strong acids. Heat sources. Sources of ignition. Direct sunlight.
Handling	Wash hands and other exposed areas with mild soap and water before eat, drink or smoke and when leaving work.

**8. Exposure controls / personal protection**

Personal protection	Avoid all unnecessary exposure.
Respiratory protection	Where excessive dust may result, wear approved mask.
Hand protection	In case of repeated or prolonged contact wear gloves.

